

## **Executive Summary**

Landscape and visual monitoring and site audits were carried on 4<sup>th</sup> and 18<sup>th</sup> October 2006. The Contractor shall take measures to improve the condition of damaged trees described in this report.

## **Environmental Site Auditing**

Damaged trees next to the administration building were still unprotected after being damaged by the adjacent construction activities.

Tree T1000 and T1011 were transplanted in this month and are in fair condition. All other transplanted trees were in fair condition. Mal-pruning of transplanted trees had not been rectified since July 2006. Construction material was still stockpiled within tree protection zones since July 2006. A statement on the cause of death of tree T925 recorded in the last report was still outstanding.

## **Recommendations and Conclusion**

Regarding the retained trees, the Contractor shall take the following measures:

- Carry out surgery to damaged trees;
- Report the cause of death of tree T925; and
- Maintain the tree protection zone required and remove all construction material / debris from the tree protection zone
- Rectify the mal-pruning practice of the transplanted trees; and
- Carry out hydroseed works at bare slopes/stockpiles when practical.